

The “Felpham” Measurement Unit for Home Brew Valve Tester

Errata.

The following modifications need to be made to the pcb supplied while assembling

1. A 1uF capacitor needs to be added from the junction of R43 / RV6 to 0V, see fig 1
2. A 9k1 resistor needs to be added from the junction of R31 / R34 / C21 to 0V see fig 2



Fig 1



Fig 2