




POWER LINE FOR CSA MODEL

BAND SWITCH
ANL SWITCH
STAND BY SWITCH
MODE (AM/SSB, CW) SWITCH
RF GAIN CONTROL
AF GAIN CONTROL/ON-OFF SWITCH
JES IN OHMS. K = 1000
LUES IN MFD. P=MMF. (M) = MYLAR
NUMBER OF COMPONENT PARTS ARE SUBJECT
IMPROVEMENT WITHOUT NOTICE.
ED ○, MEASURED BY V.T.V.M.
ED □, MEASURED BY V.T.V.M.
ITION OF RF VOLUME CONTROL MINIMUM, AF
L, AT MINIMUM, WITHOUT SIGNAL. BFO ON.